



Fastener Guide




Socket Head




Flat Head



Button Head



Hex Head



Set Screw




Fastener Availability


| Diameter and Thread Count: | Screw | | | | | Washer | | Pin | | Nut |
|----------------------------|-------|-------------|-----|-----------|-----|---------|------|-------|---------|-----|
| | SHCS | Button Head | Hex | Flat Head | Set | Regular | Lock | Dowel | Locking | |
| AMERICAN | | | | | | | | | | |
| 2-56 | X | | | | | X | X | | | X |
| 4-40 | X | X | | X | X | X | X | | | X |
| 5-40 | X | | | X | X | X | X | | | X |
| 6-32 | X | X | | X | X | X | X | | | X |
| 8-32 | X | X | | X | X | X | X | | | X |
| 10-24 | X | X | | X | X | X | X | | | X |
| 10-32 | X | X | | X | X | X | X | | | X |
| 1/16 | | | | | | | | X | X | |
| 3/32 | | | | | | | | X | X | |
| 1/8 | | | | | | | | X | X | |
| 5/32 | | | | | | | | | X | |
| 3/16 | | | | | | | | X | X | |
| 1/4-20 | X | X | X | X | X | X | X | X | X | X |
| 1/4-28 | X | X | X | X | X | X | X | X | X | X |
| 5/16-18 | X | X | X | X | X | X | X | X | X | X |
| 5/16-24 | | | X | | | | | X | X | X |
| 3/8-16 | X | | X | X | X | X | X | X | | X |
| 3/8-24 | X | | X | X | X | | | X | | |
| 7/16-14 | X | | | | X | | | | | X |
| 1/2-13 | X | | X | X | X | X | X | X | | X |
| 1/2-20 | X | | X | | | | | X | | X |
| 5/8-11 | | | | | X | | | X | | |
| METRIC | | | | | | | | | | |
| M2.5x.45 | X | | | | | X | | | | X |
| M3x.5 | X | | | | | X | | | | X |
| M4x.7 | X | | | | | X | | | | X |
| M5x.8 | X | | | | | X | | | | X |
| M6x1 | X | | | | | X | | | | X |
| M8x1.25 | X | | | | | X | | | | X |
| M10x1.5 | X | | | | | X | | | | X |



Hex Nut




Lock Washer, Star




Spring Pin



Lock Washer, Spring



Flat Washer



Dowel Pin

